Declassified in Part - Sanitized Copy Approved for Release 2013/08/21: CIA-RDP78-03424A001300050004-0

Office Memorandum • UNITED STATES GOVERNMENT

то :	The Files	DATE: 29 May 1958	
FROM :			50X1
su bject :	RD-128, T.O. 1	DOC 12 REV DATE 6 MAY BOUNS 73 ORIG COMP 033 DPI 56 TYPE 02 ORIG CLASS PAGES 7 REV CLASS C JUST 22 NEXT REV 2010 AUTH1 HR 10-2	
	premises to disc	ng was held on 26 May 1958 at the contractor's uss the progress of work under Work Order 4, ication of 35 Video Recorder Units.) of this attending were:	
`			50X1
· •			
			* 1
	2. following items:	was advised that the Agency was disturbed about the	50X1
		Out of 15 units delivered as the first part of the production run, 13 units were rejected by the Agency due to assorted defects. (See Attachment 1)	
		Thelong time involved (approximately 15 months to date) for the completion of work.	
/	C.	A lack of concentrated effort on the contractor's part.	
	đ.	Poor management of funds.	
•	e •	Poor technical ability and engineering practice.	
	On a previous oc company requeste	casion, letters of 14 and 31 March), the d additional funds to complete all remaining work order and assured the Agency at that time that	50X1
	complete workabl	e units would be delivered. Now, the Agency stated, ad a moral obligation to repair the defrective units	50X1

CONFIDENCEM: .

Declassified in Part - Sanitized Copy Approved for Release 2013/08/21 : CIA-RDP78-03424A001300050004-0

3. After a long discussion of the items listed in Paragraph 2			
and possible causes for the defects listed in Attachment 1,	50X1		
stated that, in his opinion, had met all its obligations under	50X1		
the QRF contract. also requested a formal rejection of the	50X1		
unitsin question before any corrective action could be taken. In			
addition, all parties concerned agreed that the Agency would test the			
15 units scheduled for delivery within the next several days and			
return any defective units. felt that only then could	50X1 50X1		
an honest appraisal of additional cost, if any, be prepared by			
At this point, it was made clear to that the Agency felt	50X1		
it was not its responsibility to pay the additional cost for repairing			
the defective units. agreed to consider this when they			
prepared their cost estimate.			
	5 04		
	50X1		

Attachment:

Attachment 1